

AE/LS90/TMA/24/06/23

# TO BE FILLED BY THE INSPECTING OFFICER (ASSISTANT ENGINEER)

- 1. Name of Officer : Alan Jose
- 2. Name of School : Pazhassi Raja School Kuthampully
- 3. Location / with Name of Education District / Sub District : Kuthampully Thiruvilwamala
- 4. Classification of Building and Size : Rec Building (CIF only) 1080.85 m<sup>2</sup>
- 5. Period of which the Certificate Issued : 2023-24  
II nd building 2357.08 m<sup>2</sup>

- 6. Nature of Defects if any
    - a) Foundation & Basement
    - b) Superstructure
    - c) Doors & Windows
    - d) Wood work wroughts put up
    - e) Roof
    - f) Flooring
    - g) Miscellaneous (cracks etc)
- } NIL

7. Any major defects noticed which will render the building unsafe in any manner:

8. Whether maintenance works have been done properly : Yes


9. Whether the structure is sound on for Conducting classes : sound under normal and weather conditions

- Note :
- 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.
  - 2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate

Certified that the school was inspected by me on 24/06/2023 and found to be fit/unfit to conduct classes for the period 2023-24 for the reasons noted above.

Place : Thiruvilwamala  
Date : 24/06/2023

  
 PRINCIPAL  
 PAZHASSIRAJA SCHOOL  
 KUTHAMPULLY  
 THIRUVILWAMALA - 680 594  
 Designation

  
 MANAGER  
 PAZHASSIRAJA SCHOOL  
 KUTHAMPULLY  
 THIRUVILWAMALA - 680 594